



กรมการบินพลเรือน ประเทศไทย

DEPARTMENT OF CIVIL AVIATION, THAILAND

ใบรับรองหน่วยซ่อม

REPAIR STATION CERTIFICATE

เลขที่ / NUMBER 463/2554

ใบรับรองฉบับนี้ออกให้กับ

THIS CERTIFICATE IS ISSUED TO

ATLAS AEROSPACE ACCESSORIES, INC

7820 N.W. 56th STREET MIAMI, FL 33166, USA

ซึ่งปรากฏว่า องค์กรนี้มีการดำเนินการเป็นไปตามข้อบังคับทั้งหมดของกรมการบินพลเรือน ว่าด้วยระเบียบที่เกี่ยวกับการจัดตั้งหน่วยซ่อม และมีสิทธิปฏิบัติการเป็นหน่วยซ่อมที่ได้รับความเห็นชอบได้

UPON FINDING THAT ITS ORGANIZATION COMPLIES IN ALL RESPECTS WITH THE REQUIREMENTS OF THE DEPARTMENT OF CIVIL AVIATION REGULATIONS RELATING TO THE ESTABLISHMENT OF A REPAIR STATION, AND IS EMPOWERED TO OPERATE AN APPROVED REPAIR STATION.

ด้วยขีดความสามารถดังต่อไปนี้ :

WITH THE FOLLOWING RATINGS :

LIMITED INSTRUMENT
ACCESSORY

ถ้ามิได้ถูกเรียกคืน พักใช้ หรือ เพิกถอน ใบรับรองนี้มีผลใช้บังคับ

THIS CERTIFICATE, UNLESS CANCELLED, SUSPENDED, OR REVOKED, SHALL CONTINUE IN EFFECT

นับจาก / FROM APRIL 16 , 2011 จนถึง / TO APRIL 15 , 2014

วันที่ออก / DATE ISSUED :

APRIL 16 , 2011



ใบรับรองฉบับนี้ไม่สามารถโอนได้ การเปลี่ยนแปลงสิ่งอำนวยความสะดวกใดๆ ในสาระสำคัญ หรือสถานที่ตั้ง จะต้องรายงานให้กรมการบินพลเรือนทราบโดยเร็ว

THIS CERTIFICATE IS NOT TRANSFERABLE, AND ANY MAJOR CHANGE IN THE BASIC FACILITIES, OR IN THE LOCATION THEREOF, SHALL BE IMMEDIATELY REPORTED TO THE DEPARTMENT OF CIVIL AVIATION, BANGKOK, THAILAND.



กรมการบินพลเรือน ประเทศไทย

DEPARTMENT OF CIVIL AVIATION, THAILAND.

ข้อกำหนดรายละเอียดการปฏิบัติการหน่วยซ่อม

REPAIR STATION OPERATIONS SPECIFICATIONS

ข้อจำกัด / LIMITATIONS :

ขีดความสามารถที่กำหนดในใบรับรองหน่วยซ่อม เลขที่ ๔๖๓/๒๕๕๔ ได้รับการจำกัดไว้ดังต่อไปนี้ :

THE RATING (S) SET FORTH ON REPAIR STATION CERTIFICATE NUMBER 463/2554

IS / ARE LIMITED TO THE FOLLOWING :

LIMITED INSTRUMENT

LIMITED TO MAINTENANCE AND ALTERATION OF COMPANY'S APPROVED CAPABILITY LIST, AS AMENDED.

ACCESSORY : CLASS 1, 2 & 3

LIMITED TO MAINTENANCE AND ALTERATION OF COMPANY'S APPROVED CAPABILITY LIST, AS AMENDED.

ALL WORK MUST BE DONE IN ACCORDANCE WITH CURRENT MANUFACTURER'S MAINTENANCE MANUALS OR INSTRUCTIONS FOR CONTINUED AIRWORTHINESS OR OTHER METHODS, TECHNIQUES AND PRACTICES ACCEPTABLE TO THE DCA.

วันที่ออก / DATE ISSUED :

APRIL 16, 2011



Saengchai Wisitcharoenst
Acting Director of Flight Standards Bureau
พนักงานเจ้าหน้าที่ / COMPETENT OFFICIAL

No. 0506 /INT 2961



Flight Standards Bureau
Department of Civil Aviation
71 Soi Ngamduplee, Rama IV Road
Bangkok 10120, THAILAND
Tel: (66-2) 287-0923
Fax: (66-2) 286-2913

September 26 , B.E. 2557 (2014)

Dear Sir,

Subject: The validity extension of Repair Station Certificate No. 463/2554

Reference is made to our letter no. 0506/INT 932 dated March 24, 2014 concerning the Repair Station Certificate renewal.

In this regard, please kindly be informed that we are inconvenient to audit Atlas Aerospace Accessories Inc., USA at the moment. This letter is to certify the extension of Repair Station Certificate No. 463/2554 until March 31, 2015 subject to the Department of Civil Aviation audit as deemed necessary.

Please do not hesitate to contact us for any information concerned.

Yours sincerely,



(Wiwit Deepradit)

Director of Flight Standards Bureau

Attn: Miguel Boro
Chief Inspector
Atlas Aerospace Accessories Inc.
Tel: 305.717.9951
Fax: 305.717.9947

No. 0506 /INT 932



Flight Standards Bureau
Department of Civil Aviation
71 Soi Ngamduplee, Rama IV Road
Bangkok 10120, THAILAND
Tel: (66-2) 287-0923
Fax: (66-2) 286-2913

March 24, B.E. 2557 (2014)

Dear Sir,


Subject: The validity extension of Repair Station Certificate No. 463/2554

Reference is made to your letter dated March 11, 2014 concerning the Repair Station Certificate renewal.

In this regard, please kindly be informed that we are inconvenient to audit Atlas Aerospace Accessories Inc., USA at the moment. This letter is to certify the extension of Repair Station Certificate No. 463/2554 until September 30, 2014 subject to the Department of Civil Aviation audit as deemed necessary.

Please do not hesitate to contact us for any information concerned.

Yours sincerely,



Wiwit Deepradit

Director of Flight Standards Bureau

Attn: Miguel Boro
Chief Inspector
Atlas Aerospace Accessories Inc.
Tel: 305.717.9951
Fax: 305.717.9947